


## Transistor / resistor verification




Radiant mode, 12mm gap, LA1@input, A@output, 7 power coils. Input +/-1amp


Prope 1: ground to negative of input battery, positive to collector transistor 1

Prope 2: ground not connected, positive to collector transistors 2,3,4,5,6,7


# Transistor1 and 2 - x1 - 200us 5V




### Transistor1 and 2 - x200




### Transistor1 and 3 - x200




### Transistor1 and 4 - x200



### Transistor1 and 5 - x200



### Transistor1 and 6 - x200



### Transistor1 and 7 - x200

