



put the power source of R7 at the output of the positive regulator,
Pin3, instead connect to the output of the beta multiplier

R2 and LED1 need to be connected in parallel,

R16 added negative feed back to Servo op amp

R17 changed designation of 5W resistor from R16 to R17

Linear Amp Regulator		
Modified Nityesh Schematic		
Ecananvas	Rev 3.0	
	9/23/2014	